

Addendum to the Release Notes for the Accelar 1000 Series Products

Software Release 1.1.4

4401 Great America Parkway
Santa Clara, CA 95054

8 Federal Street
Billerica, MA 01821

Part No. 202693-A
July 1998



Bay Networks



* 2 0 2 6 9 3 - A *

Copyright © 1998 Bay Networks, Inc.

All rights reserved. Printed in the USA. July 1998.

The information in this document is subject to change without notice. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Bay Networks, Inc.

Trademarks

Bay Networks and Optivity are registered trademarks of Bay Networks, Inc.

Accelar, LinkSafe, and the Bay Networks logo are trademarks of Bay Networks, Inc.

All other trademarks and registered trademarks are the property of their respective owners.

Statement of Conditions

In the interest of improving internal design, operational function, and/or reliability, Bay Networks, Inc. reserves the right to make changes to the products described in this document without notice.

Bay Networks, Inc. does not assume any liability that may occur due to the use or application of the product(s) or circuit layout(s) described herein.

Introduction

This release note addendum for Accelar software release 1.1.4 describes the bug fixes to the Bay Networks® Accelar™ Software that have been implemented since release 1.1.1 and the known problems that exist in release 1.1.4. This document is an addendum to the *Release Notes for the Accelar 1000 Series Products Software Release 1.1.1* (Bay Networks part number 896-00181-C) and includes references to those fixes incorporated into interim releases 1.1.2 through 1.1.4.

Software release 1.1.4 includes updates to the run-time software only. Refer to the Release Notes (part number 896-00181-C) for instructions on how to download the software and descriptions of software features and limitations.



Note: Release 1.1.4 is for Accelar 1100/1150 and Accelar 1200/1250 Routing Switches only. This release is not for Accelar 1050/1051 switches.

Bugs Fixed in This Release

This section lists the bugs from release 1.1.1 that have been fixed in later releases. For clarification, they are listed by the specific interim release in which the fix occurred.

Release 1.1.2

The following bugs were fixed in release 1.1.2:

- The Accelar switch did not forward DHCP negative acknowledgments (NAKs).
- The RcvBadRoutes counter did not increment when a bad metric was received for RIP.
- Multicast MAC addresses were not accepted in ARP response packets.
- Too many ARP requests were sent out in response to the deletion of a MAC address.
- Data corruption occurred on back-to-back frames sent out by the CPU.

Release 1.1.4

The following bugs were fixed in release 1.1.4:

- An expired timeout value for a configuration BPDU was ignored and the BPDU was not dropped, which resulted in the root bridge oscillating between two bridges.
- When a RIP-learned route timed out and there was a less specific static route configured, the timed-out route was not deleted.

Known Problems in Release 1.1.4

The following are known problems in the 1.1.4 release:

- Management “blackouts” occur as a result of synchronous cleanup of MAC address records in the ARU.
- In some configurations, there are no responses to ARP requests.
- In Gigabit Ethernet ports, the LinkSafe™ redundant port does not take over when the receive connection is lost and the transmit connection is operating correctly.
- A less specific static route removes a more specific learned route. Also a learned route cannot be added if a less specific static route is configured.
- An IP subnet broadcast or a ping of a local IP address from the console causes the Accelar switch to run out of frame buffers.
- The Accelar switch stops processing IP packets when it receives a packet destined for itself.
- RIP updates with a next hop address field of the Accelar VLAN address lose the VLAN IP address.
- When the switch fabric is busy, CPU-generated traffic (for example, BPDUs) may egress the switch with FCS errors. This problem may also appear as a management slowdown.